

PT100

-50°C	80,31 Ohm
-40°C	84,27 Ohm
-30°C	88,22 Ohm
-20°C	92,16 Ohm
-10°C	96,09 Ohm
0°C	100,00 Ohm
+10°C	103,90 Ohm
+20°C	107,79 Ohm
+25°C	109,74 Ohm
+30°C	111,67 Ohm
+40°C	115,54 Ohm
+50°C	119,40 Ohm
+60°C	123,24 Ohm
+70°C	127,07 Ohm
+80°C	130,89 Ohm
+90°C	134,70 Ohm
+100°C	138,50 Ohm
+110°C	142,29 Ohm
+120°C	146,06 Ohm
+130°C	149,82 Ohm
+140°C	153,58 Ohm
+150°C	157,31 Ohm

www.sensorshop24.de