

FeT

-50°C	
-40°C	
-30°C	1934,70 Ohm
-20°C	2030,41 Ohm
-10°C	2127,68 Ohm
0°C	2226,53 Ohm
+10°C	2327,01 Ohm
+20°C	2429,15 Ohm
+25°C	2480,86 Ohm
+30°C	2533,00 Ohm
+40°C	2638,60 Ohm
+50°C	2745,99 Ohm
+60°C	2855,23 Ohm
+70°C	2966,36 Ohm
+80°C	3079,42 Ohm
+90°C	3194,47 Ohm
+100°C	3311,56 Ohm
+110°C	3430,75 Ohm
+120°C	3552,09 Ohm
+130°C	3675,65 Ohm
+140°C	3801,48 Ohm
+150°C	3929,65 Ohm

www.sensorshop24.de