

Ni1000

-50°C	743,00 Ohm
-40°C	791,00 Ohm
-30°C	842,00 Ohm
-20°C	893,00 Ohm
-10°C	946,00 Ohm
0°C	1000,00 Ohm
+10°C	1056,00 Ohm
+20°C	1112,00 Ohm
+25°C	1141,00 Ohm
+30°C	1171,00 Ohm
+40°C	1230,00 Ohm
+50°C	1291,00 Ohm
+60°C	1353,00 Ohm
+70°C	1417,00 Ohm
+80°C	1483,00 Ohm
+90°C	1549,00 Ohm
+100°C	1618,00 Ohm
+110°C	1688,00 Ohm
+120°C	1760,00 Ohm
+130°C	1883,00 Ohm
+140°C	1909,00 Ohm
+150°C	1987,00 Ohm

www.sensorshop24.de